EXTENSION SOCKETS - MORSE TAPER

Hardened Tang, accurately ground externally.

Part No.	Equivalent Size	Morse Outside	Taper Inside
XMT1MT1	-	1	1
XMT1MT2	-	1	2
XMT2MT1	821	2	1
XMT2MT2	-	2	2
XMT2MT3	-	2	3
XMT3MT1	831	3	1
XMT3MT2	832	3	2
XMT3MT3	-	3	3
XMT3MT4	-	3	4
XMT4MT1	-	4	1
XMT4MT2	842	4	2
XMT4MT3	843	4	3
XMT4MT4	-	4	4
XMT4MT5	-	4	5
XMT5MT1	-	5	1
XMT5MT2	-	5	2
XMT5MT3	853	5	3
XMT5MT4	854	5	4
XMT5MT5		5	5



EJECTING DRIFTS

To eject Morse Tapers from sleeves, sockets and machine spindles.
4 Hardened and tempered

Part No.	To Eject
EDMT0	0 Morse Taper
EDMT12	1 & 2 Morse Taper
EDMT34	3 & 4 Morse Taper
EDMT45	4 & 5 Morse Taper
EDMT6	6 Morse Taper
DD1MTA	1 Morse Taper
DD2MTA	2 Morse Taper
DD3MTA	3 Morse Taper
DD4MTA	4 Morse Taper
DD5MTA	5 Morse Taper
DD1-2MTEA	1 & 2 Morse Taper
DD2-3MTEA	2 & 3 Morse Taper
DD3-4MTEA	3 & 4 Morse Taper

